


GSET

Assembly Instructions

Kit Contents:

1-Table Top
4-Legs
16-1-3/4" Screws



Step 1: Lay the table top upside down on a clean surface.

Step 2: Place the leg over the corner of the table. Insert the screws into the bottom pre-drilled holes in the table first. **See Photo #1**

Step 3: While holding pressure on the leg against the table frame, tighten the bottom screws in place. Repeat with the top screws. Each leg gets four screws.

Step 4: Repeat with the remaining three legs.




Photo #1



For questions or ordering information contact
The Maine Bucket Company's customer service at 1-800-231-7072
www.mainebucket.com